

IQinVision

Software Release Note History
Product: IQaccess Client Software
Version: 1.1.2
Date: June 2011

Copyright 2011, IQinVision

Release Summary

This document describes the IQinVision 1.1.2 IQaccess client software release documenting new features and bug fixes since V1.1.0 software release.

Version: V1.1.2

Date: 06/2011

New Features / Enhancements:

1. IQaccess button text now decodes numeric HTML entities.

Big Fixes:

1. None
-

Version: V1.1.1

Date: 02/2011

New Features / Enhancements:

1. IQaccess button now accepts special characters.
2. Popup window minimum size.
3. Popup window background matches the image background.

Bug Fixes:

1. The 1:1 aspect ratio of the IQaccess window causing the images to be squeezed horizontally has been fixed.
-

Version: V1.1.0

Date: 06/2010

New Feature / Enhancements:

1. Remote camera properties are updated when the user clicks refresh.
2. Audio alerts are played when IQaccess receives a trigger and when a pop-up window is displayed.
3. The following preferences close options have been added:
 - Close pop-up automatically
 - Close pop-up after 5-minutes
 - Close pop-up manually
4. Additional enhancements for use with 3rd party access control.
5. RTSP over TCP implemented for "Press To Talk" operation.
6. Audio operates in press to talk and release to listen mode.

Bug Fixes:

1. Cached audio has been removed.
 2. Cameras with "Connection Lost" status disappears after reconnecting is now fixed.
-

Version: V1.0.8

Date: 01/2010

New Feature / Enhancements:

1. Pressing “Talk” button captures audio, and stops when the “talk” button is released.
2. XML file for 3rd party access control systems can handle multiple commands.
3. Check for VLC, and Active X control is registered if not reminder message will be displayed.
4. .NET library (libvlcnet) replaces the VLC ActiveX control.

Bug Fixes:

1. Cameras with MAC address 00:50:1a:07:22:XX could become unregistered after IQaccess is restarted is fixed.
 2. IQaccess stops responding on clicking the “door Release” button is fixed.
 3. When computer is removed from network and put back on the network causes the camera connection to not remain is fixed.
 4. User can proceed past the register camera dialog box if the user doesn’t select any signal options.
 5. Trigger pop-up will not stream H.264 video if the IQ732 series camera is set to MJPEG 1080p mode.
 6. Link in help was fixed.
-

Version: V1.0.5

Date: 11/2009

New Features / Enhancements:

1. 3rd party access control support added for Axxess [Maxxess].
2. Allow only the administrator to change preferences, register/unregister cameras, and add/delete remote cameras.
3. Audio alert when H.264 trigger window is displayed.

Bug Fixes:

1. Byte stream sent to Maxxess multiport server has been fixed.
-

Version: 1.0.3

Date: 10/2009

New Features / Enhancements:

1. “Enable Talk” and “Enable Listen” preferences have been added.
2. VLC plug-in has been added for H.264 video streams.
3. Audio added for IQ732 series cameras.

Bug Fixes:

1. None
-

Version: V1.0.1**Date:** 06/2009**New Features / Enhancements:**

1. Audio option “Enable Talk” and “Enable Listen” are added to the preferences for two-way audio support with IQ732xx series cameras.

Bug Fixes:

1. None.
-

Version: V1.0.0.0**Date:** 06/2009**New features / Enhancements:**

1. Initial release
2. PRO LINE cameras require firmware version V3.0/2

Bug Fixes:

1. None